



# HOSHIZAKI AMERICA, INC.

## SERVICE BULLETIN

**SB01-0004**

May 2, 2001

Page 1 of 1

**Subject: FLAKER BEARINGS AND BEARING HOUSINGS**

\*\*NOTE THIS BULLETIN SUPERSEDS PB91-0012 REV. MAY 30, 1996\*\*

MODEL NUMBER	EXTRUDING HEAD	REPLACEMENT BEARING	LOWER HOUSING	REPLACEMENT BEARING
F-250BAA	317048G02	SP88-7311	206013G03	SP88-7312
F-251B & U	317048G02	SP88-7311	206013G03	SP88-7312
F-250BAE	327140G01	SP88-7311	206013G03	SP88-7312
F-300BAF	340077G01	SP88-7311	206013G03	SP88-7312
F-440BAA	312603G02	SP88-7313	206653G02	SP88-7314
F-441U	312603G02	SP88-7313	206653G02	SP88-7314
F-450BAB/BWB	317048G02	SP88-7311	206013G03	SP88-7312
F-450BAE	327140G01	SP88-7311	206013G03	SP88-7312
F-450MAF / MAH	340077G01	SP88-7311	206013G03	SP88-7312
F-450MAF-C / MAH-C	327141G01	SP88-7311	206013G03	SP88-7312
F-500BAF	340077G01	SP88-7311	206013G03	SP88-7312
F-500BAF-C	327141G01	SP88-7311	206013G03	SP88-7312
F-650M_B/M_E	327097G01	SP88-7313	214938G01	SP88-7314
F-650M_E-C	216531G01	SP88-7313	214938G01	SP88-7314
F-800M_F / M_H	327097G01	SP88-7313	2A0947G01	SP88-7314
F-800M_F-C / M_H-C	216531G01	SP88-7313	2A0947G01	SP88-7314
F-1000M_B	321027G01	SP88-7313	211461G01	SP88-7314
F-1000M_E & -50	328801G01	SP88-7313	211461G01	SP88-7314
F-1000M_E-C	3A1304G01	SP88-7313	211461G01	SP88-7314
F-1000M_F	327097G01	SP88-7313	2A0947G01	SP88-7314
F-1000M_F/C & -22	216531G01	SP88-7313	2A0947G01	SP88-7314
F-1100/F-1101 ALL	208117G02	SP88-7316	315732G02	SP88-7317
F-1001M_F / M_H	327097G01	SP88-7313	2A1977G01	SP88-7314
F-1001M_F-C / M_H-C	216531G01	SP88-7313	2A1977G01	SP88-7314
F-2000M_B	216407G01	SP88-7316	206509G02	SP88-7317
F-2000M_E 1/3	216407G01	SP88-7316	206509G02	SP88-7317
F-2000M_F 1/3 / M_H 1/3	216407G01	SP88-7316	206509G02	SP88-7317

**F-2000M\_F-C 1/3 / M\_H-C 1/3**

**2A1594G01**

**SP88-7316**

**206509G02**

**SP88-7317**